



## SHORT REPORT – NO VISIBLE IMPACT

Document Date: 13/11/2020

Production Site (PS): e-GEOS

Activation number: EMSR480

AOI name: AOI 07 Koumi

Product Type: GRADING

*Post-event data:*

Sensor: Pleiades

GSD (pixel size): 0.5 m

Acquisition Date and Time: **13/11/2020 09:17 UTC**



AOI 07 Koumi

*Pre-event data:*

Sensor: WorldView 1

GSD (pixel size): 0.5 m

Acquisition Date and Time: **03/05/2019 09:27 UTC**











IMAGE PERTINENCE ANALYSIS DESCRIPTION					
Why is the image not pertinent for crisis production?	<table border="1"><thead><tr><th>Pre-event data</th><th>Post-event data</th></tr></thead><tbody><tr><td><p>Pre-event situation</p></td><td><p>Post-event situation In the image acquired 13/11/2020 no visible damage compared with the pre-event image.</p></td></tr></tbody></table>	Pre-event data	Post-event data	 <p>Pre-event situation</p>	 <p>Post-event situation In the image acquired 13/11/2020 no visible damage compared with the pre-event image.</p>
Pre-event data	Post-event data				
 <p>Pre-event situation</p>	 <p>Post-event situation In the image acquired 13/11/2020 no visible damage compared with the pre-event image.</p>				
Result of analysis	The image quality has been assessed as appropriate for the GRADING analysis. In the covered area, no visible damages have been identified.				
Methodology used	Photo-interpretation.				
Additional comments	The analyzed images fully covers the AOI.				



IMAGE PERTINENCE ANALYSIS DESCRIPTION		
Why is the image not pertinent for crisis production?	<b>Pre-event data</b>  Pre-event situation	<b>Post-event data</b>  Post-event situation In the image acquired 13/11/2020 no visible damage compared with the pre-event image.
	Result of analysis	The image quality has been assessed as appropriate for the GRADING analysis. In the covered area, no visible damages have been identified.
Methodology used	Photo-interpretation.	
Additional comments	The analyzed images fully covers the AOI.	



Copernicus EMS Rapid Mapping  
**Short Report – No visible impact**

